

## FIELD INSPECTION

<b>Project Name:</b>	Mountain Valley Pipeline	<b>Inspector:</b>	Matthew Grant
<b>Inspection Date:</b>	Thursday, October 25, 2018	<b>Project Contact:</b>	Brian Clauto
<b>Spread: Montgomery County MP230-MP232 St#12153-12297</b>	Spread H	<b>Weather (Wet/Dry/Rain):</b>	Dry

**STAGE OF CONSTRUCTION:** (Check all that apply)

- ☐ Clearing
 ☐ Rough Grading
 ☒ Trench Excavation
 ☒ Pipe Assembly, Testing & Installation  
☒ Backfilling and Grade Restoration
 ☐ Final Grading & Stabilization
 ☐ Other:

- |   |   | Yes                                 | No                                  | N/A                      |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?                                       | <input checked="" type="checkbox"/> | <input type="checkbox"/>            | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed?   | <input type="checkbox"/>            | <input checked="" type="checkbox"/> | <input type="checkbox"/> |


**Comments:**

- **Area 1** – MP 229 -232
- St#12158 water bar flow path requires maintenance
- St#12163 silt sock is torn and requires replacement
- St#12167 silt sock is torn and requires replacement
- St#12184+60 waterbar requires maintenance and to be re constructed per the spec.
- St#12185+58 waterbar requires maintenance and to be re constructed per the spec.

**Recommended Corrective Action:** replace and maintain all controls per the annual standard and specs.

**Deadline:** Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 11-8-18

## FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, October 25, 2018

- Fig. 1 St#12158 water bar flow path requires maintenance



- Fig. 2 St#12167 silt sock is torn and requires replacement



- Fig. 3 St#12184+60 waterbar requires maintenance and to be re constructed per the spec.



- Fig. 4 St#12185+58 waterbar requires maintenance and to be re constructed per the spec

